which be dominated the comment of th	JUASSITIED WESSAGE [) same ames na 80	PFS ChSt cree Charles Construction of Construc- UTING	
DATE 2147Z 23 DWC S4	ξ [-	2	9 10 11	~. •.
25 X1A	The second secon	d 5	12	
TO : DIRECTOR	11	6 7 3	14 15 16	
ACTION:	3	PRIORITY		
TOR 2215Z 23 DEC 64 25X1A	7 8 8 10 10		W 64351	
TO PRIORITY INFO 25X1A OXCART FLIEST OPS		CITE	003,83	X1A
25X1A 1. ARTICLE 128 MADE FL	IGHT 68, SORTIE 1-M-64- AT 0915 HOURS, LANDING		٠,	tv. v

- 55 MINUTES. MISSION UNSUCCESSFUL. GROSS WEIGHT 90,000 LBS, C.G. 21.4 PERCENT, TAKEOFF DISTANCE 7500 FT, TAKEOFF SPEED 210 KNOTS, PRESSURE ALT 4375 FT, TEMP 41 DEGREES, WIND CALM, MAX SPEED 2.80 MACH, MAX ALT74,800 FT, TIME OVER 2.0 MACH :30, TIME OVER 2.6 MACH :20, TOTAL AIRCRAFT TIME 112:53. PURPOSE: FUNCTION CHECK FLIGHT. COMFIGURATION: 2.9 MACH. Q BAY AND SPECIAL EQUIPMENT: NOME.
- 2. HORNAL TAKEOFF AND CLINB. INS AUTOMAV- AUTO DESTINATION USED AND APPEARED GOOD. 3 AD°S WITH AB BLOW OUT OCCURED ON LEFT ENGINE ABOVE 2.6 MACH. CONSIDERABLE ENGINE TRINNING WAS REQUIRED THROUGHOUT THE FLIGHT. SAS YAW B CHANNEL MALFUNCTIONED DURING CLIMB OUT BUT RESET WITH NO PROBLEM IT AGAIN MALFUNCTIONED ON GROUND CHECK AFTER LANDING, CAUSE UNKNOWN. ON LANDING, CHUTE DEPLOY/JETTISON MORNAL.

END OF MESSAGE

USAF review(s) completed.

SECRET

GROUP 1 ERGLUDED FROM AUTO-MATIC DOWNGRADING AND DECLASSIFICATION

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.